

U.S. DEPARTMENT OF LABOR

Form No. OSHA-20
June 1971

Occupational Safety & Health Adm.
MATERIAL SAFETY DATA SHEET

SECTION I	
MANUFACTURER'S NAME FARBEST CORPORATION	EMERGENCY TELEPHONE NO. (213) 758-3181
ADDRESS (Number, Street, City, State, and ZIP Code) 6715 McKinley Ave. Los Angeles, Ca. 90001	
CHEMICAL NAME AND SYNONYMS Not Applicable	TRADE NAME AND SYNONYMS #472 Soluble Oil
CHEMICAL FAMILY Not Applicable	FORMULA

SECTION II HAZARDOUS INGREDIENTS					
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Units)
Within the definition of hazardous materials contained in the Longshorman's and Harbor Workers compensation Act (33VSC941) Section 1501.2 ammended, this product is not hazardous.					

SECTION III PHYSICAL DATA			
BOILING POINT (°F.)	385 F	SPECIFIC GRAVITY (H ₂ O=1)	0.920
VAPOR PRESSURE (mm Hg.)	NA	PERCENT VOLATILE BY VOLUME (%)	NA
VAPOR DENSITY (AIR=1)	NA	EVAPORATION RATE (_____ =1)	NA
SOLUBILITY IN WATER	Soluble		
APPEARANCE AND ODOR	Oily liquid, slight lemon odor.		

SECTION IV FIRE AND EXPLOSION HAZARD DATA			
FLASH POINT (Method used)	390 F (C.) C.)	FLAMMABLE LIMITS	NA
EXTINGUISHING MEDIA	Foam, CO ₂ , Dry chemical	LeI	Uel
SPECIAL FIRE FIGHTING PROCEDURES	None		
UNUSUAL FIRE AND EXPLOSION HAZARDS	None		

DPM 5732

SECTION V - HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE	Observe current ACGIHTLV of 5mg/m ³ for oil mists.
EFFECTS OF OVEREXPOSURE	Dermatitis in very sensitive individuals after extended exposure (Days).
EMERGENCY AND FIRST AID PROCEDURES	Skin contact should be avoided. Wash with soap and water. Eye contact wash with copious quantity of water.

SECTION VI - REACTIVITY DATA			
STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	<input checked="" type="checkbox"/>	Avoid contact with strong oxidizing agents. high concentrations of O ₂
INCOMPATIBILITY (Materials to avoid) Excessive overheating may form oxides of sulfur			
HAZARDOUS DECOMPOSITION PRODUCTS			
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	<input checked="" type="checkbox"/> X*	
* Under normal operating conditions.			

SECTION VII - SPILL OR LEAK PROCEDURES	
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	Absorption, wipe or soak up, wash with safety solvent and/or detergent and water.
WASTE DISPOSAL METHOD	Absorption, controlled burning, Observe local, state, federal regulation in disposing of lubricant.

SECTION VIII - SPECIAL PROTECTION INFORMATION		
RESPIRATORY PROTECTION (Specify type)		
VENTILATION	LOCAL EXHAUST	SPECIAL
	MECHANICAL (General)	OTHER
PROTECTIVE GLOVES		EYE PROTECTION
Should be worn.		
OTHER PROTECTIVE EQUIPMENT		
Barrier creams for very sensitive individuals.		

SECTION IX - SPECIAL PRECAUTIONS	
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	Normal for petroleum lubricants.
	Keep clean and dry.
OTHER PRECAUTIONS	